




TABLA DE MEDIDAS INDUSTRIALES

<u>TALLA EN BRA</u>	32B	34B	36B	38B	40B	42B	44B	46B
<u>TALLA PANTIE</u>	CH	MED	GDE	EG	2XG	3XG	4XG	5XG
CONTORNO CUELLO	35	36	37	38	39	40	41	42
CONTORNO PECHO	85	90	95	100	105	110	115	120
CONTORNO SUBMAMARIO	70	75	80	85	90	95	100	105
CONTORNO CINTURA	65	70	75	80	85	90	95	100
CONTORNO CADERA	90	95	100	105	110	115	120	125
CONTORNO SISA	38	40	42	44	46	48	50	52
CONTORNO MUSLO	53	56	59	62	65	68	71	74
CONTORNO MEDIO MUSLO	47	50	53	56	59	62	65	68
LARGO CUELLO	6.8	7	7.2	7.4	7.6	7.8	8	8.2
LARGO PECHO	25.5	26	26.5	27	27.5	28	28.5	29
LARGO SUBMAMARIO	32	33	34	35	36	37	38	39
LARGO CINTURA	42	43	44	45	46	47	48	49
LARGO CADERA	58.5	60	61.5	63	64.5	66	67.5	69
LARGO TIRO	68.5	70	71.5	73	74.5	76	77.5	79
LARGO ENTREPIERNA (DE T	78	79	80	81	82	83	84	85
LARGO CADERA (DESDE CIN	16	17	18	19	20	21	22	23
LARGO TIRO (DESDE CINTU	26	27	28	29	30	31	32	33
LARGO PANTALON	95	96	97	98	99	100	101	102
ANCHO HOMBRO	12.7	13	13.3	13.6	13.9	14.2	14.5	14.8
ANCHO ESPALDA	36	37	38	39	40	41	42	43